Histan missing means	J	4720-203-2668 Hose	REP	1.6 10	.04
BRAKE SYSTEM		001 1250 Nut	REP REP	1 EA 14 EA	. 19 . 03
Replace damaged brake line connector	16.5	5310-359-0458 Gasket	REP	2 EA 1 EA	7.91
	4.0	Steel sheet Connector brake line	REP	1 EA	
Replace 1 ea of damaged master cylinder Replace 1 ea of damaged master cylinder flexible line, then remove rust and dust for flexible line, then remove rust and dust for flexible line, then remove rust and dust for	.5		REP	1 EA	. 14
the rest. Check air-hydraulic cylinder after master cylinder	15.0	2910-741-2506 Spring 2510-737-3292 Weather	REP	1 EA 2 EA	. 54 5. 15
repair. Replace damaged wheel cylinder and bleeder valve.	2.5	2540-050-0813 Blade	REP	1 EA 1 EA	3.68
Adjust hand brake system-		2540-741-0602 00001	REP	2 EA	.708
WHEEL HUBS AND BEARING	•	- 0540 741 0704 Arm			
					Burney

# AID'S MISMANAGEMENT OF THE EXCESS PROPERTY PROGRAM

I hereby certify that I have inspected and ascertained the above cited item of equipment to be in a good serviceable condition and have accepted the work performed thereon in its entirety.

Wetner M Harness ACCEPTANCE CERTIFICATE

WELDEN M. HARNESS,
AID Marshalling Site Superintendent,
Contract No. AID/csd/1129.

## MAINTENANCE REQUEST

### SECTION 1

Control number; Aid to No. 4243-57.

14. Organization; AID EPRO NO. 5, % American Embassy, Tokyo.

Serial number; 20987.

Noun nomencleture. Truck Corgo 21/2 top W/O WINCH M 211 Serial number; 20987.

3. Noun nomenclature; Truck Cargo 2½ ton W/O WINCH, M-211.

ACQ. COST 5,993.

Rehabilitation on ATD work appelled to the control of t

Rehabilitation on AID work specifications, Appendix A, Contract AID/csd/1129 (estimated total man-hours: 238.50).

(estimated total man-hours: 250.50).	COMPLISHED	
ENGINE AND ENGINE COMPONENTS. WOODS	Gasket 10-2071 Flap PEP 2 EA	\$5.54 .66 .90 1.84 32.60 .90 9.56 9.56 9.02