SAFETY RECOMMENDATIONS SUBMITTED DURING FISCAL YEAR 1963—Continued

Recommendation		nmendation	Recommendation	Pag No
	No.	Date		
-	63–12	Aug. 24, 1962	Shifting system be revised to allow operation of bypass valve before mechanical	
	63–13	Aug. 28, 1962	control linkage is shifted	
	63–14	Sept. 5,1962	facilities. FAA take a look at configurations to be used in new 3-class passenger service in Boeing 707 type aircraft to assure that proper access to over-wing exits is main-	
	63–15	Sept. 11, 1962	tained Review quality of welds by manufacturer to insure that other Mooney aircraft are not being operated in an unsafe condition	
	63–16	Sept. 24, 1962	Operators of C-46 aircraft be required to inspect, lubricate as necessary and make functional checks of the fire extinguishing system at intervals of approximately	
	63–17 63–18	Sept. 25, 1962 Oct. 4, 1962	6 months. AD be issued requiring temporary deactivation of the Spartan electric trim system. That action be taken by Administrator to assure that radar personnel and facilities at Shemya meet FAA standards. The the face of the person of the substituted for "true radial" in designation of	
	63–19	Oct. 8, 1962		
	63–20	do	facilities at Michige-Tysun Airbuil. Also FAA provide technical assistance and	
	63–21	Oct. 11,1962	cooperation to fullest extent possible at said airport. Recommend design change in fore and aft cyclic system, Bell 47G-2, and subsequent models. Conduct 1-time inspection of fore and aft cyclic as interim safety pre-	
	63-22	Oct. 18, 1962	caution Inspection procedures Flying Tiger Line be reviewed and improvements be required to eliminate fuel contamination	
	63–23	Oct. 24, 1962	FAA examine maintenance and operating practices, riving ligers, in detail to assure	
	63-24	Oct. 25, 1962	acceptable level of airworthiness. Recommend FAA expedite matters to issue official stand at earliest possible date re recap requirements either by a TSO or MSO.	
	63-25 63-26	Oct. 29, 1962 Oct. 30, 1962	CAB endorses FAA efforts to develop flight recorders, measuring added parameters Recommend FAA conduct research to determine proper operational height for anemometers, preferred location(s) of wind measuring equipment on runway	
	63–27	Oct. 31, 1962	complex_ Pilots' examinations relative to flight characteristics and emergency procedures—	
	63–28	Nov. 5, 1962	single-engine, high-performance aircraft. Abbreviated departure message be transmitted by service B teletype on all nonair carrier a/c for delivery and action required by ATS facilities serving destination airport.	
	63-29 63-30	do	Fa a	
	63-31	Nov. 7, 1962	Mandatory corrective action be taken to modify door hinge mechanism. Consideration be given during FAA study of flight time limits to need for clearly defined criteria in adequacy of airborne rest facilities and duty time limits.	
	63-32	Nov. 8, 1962	Weather Bureau consider revising delineation system, aviation forecast areas to facilitate proper interpretation of forecasts. Improvements be made in area of liferaft stowage, lights on rafts and jackets: TSO—	
	63-33 63-34	do Nov. 15, 1962	C13 be reviewed; adequacy of seat tiedown; emergency information be issued FAA provide that data re effective altitudes on this airway be displayed more prom- inentaly on all aeronautical charts. Provide special Notams and alert bulletins as	
	63–35	Nov. 20, 1962	means of alerting unsuspecting pilot of danger in this undesignated airspace. Appropriate procedural documents of ATC be amended to require ARTC radar controllers indicate positively to pilot when radar handoff is to be employed in connec-	
	63-36	Nov. 21, 1962	tion with his flightCited approach plate remarks he amplified to include statement that no centerline	
	63-37	Dec. 19, 1962	guidance may be available during final stages of approach. See LTR Sept. 9, 1963 ATC personnel be authorized to refuse approach clearance to aircraft in weather	
	63–38	Nov. 28, 1962	conditions below lowest minimums applicable to requested approach. FAA arrange with DOD to provide periodic scheduled lectures by FAA ATC personnel re ATC operating procedures at military bases where undergraduate jet	
	63-39	Dec. 13, 1962	Immediate action be taken to effect changes outlined in letter. Discrepancies in	
		Dec. 19,1962	Airman's Guide, ILS. ATS procedures be revised to require operationally significant weather information pertinent to approach areas involved be transmitted routinely to approaching air-	
		Dec. 26, 1962	craft. Study be made by FAA of physical layout of RVR readout displays at Idlewild and	
			Runway visibility observing program be initiated at such locations when measurements not available and prevailing visibility or pilot reported visibility is 1 mile or	
			Consideration be given to development of stailing plans and work sciencies so designed that during periods of adverse weather, one of the observers on duty at a airport stations is relieved of all responsibility other than that of maintaining con-	
	63-44	Dec. 27, 1962	Stant Watch on Weather and lectoring observations. That Weather Bureau consider revision of current aviation weather observing instructions regarding "partial obscuration". Duplicate letter to FAA urged matter be discussed jointly by Weather Bureau and	
	6 3–45	Dec. 26, 1962	FAA Renresentatives of DOS will be available for consultation.	
	6 3–46	Dec. 31, 1962	Recommend current airworthiness requirements for automatic flight control systems in sec. 4b.612 of CAR and related CAM policy material as applied to high-speed swept-wing design turbojet aircraft be reevaluated for establishing realistic-performance criteria.	