[Total man-hours, 276.5; total man-hour cost, \$461.76; total parts cost, \$758.64]—Continued

Description	Man- hours (hours and 10ths)	Federal stock No.	Part source code	Quantity	Parts cost
SHEET METAL					
Repair crack and corrosion of engine hood Plug up a hole at removed left heater and remove its bracket. body and then paint all surfaces. LUBRICATING	3.0 1.0	5340-282-7521 Clip	REP REP REP REP LP LP	3 EA 6 EA 2 EA 1 EA 1 FA 2 EA 1 EA	\$.21 .30 5.00 3.20 22.90 .56
Grease up and fill oil in accordance with lubrication chart.	2. 5	2530-741-2117 Spring 2805-741-1611 Valve 2805-741-1721 Ring	LP.	4 EA 4 EA 1 SET	1. 11 2. 67 6. 38
INSPECTION Perform initial, in process and final inspection Total Excess	276. 50 38. 00	5310-281-1250 Nut 2540-741-693 Curtain	LP LP LP LP LP LP LP LP LP	1 EA 1 EA 1 EA 1 EA 1 EA 1 5 EA 2 EA 3 EA 2 EA 2 EA 2 EA	. 18 . 18 . 04 9. 11 . 01 . 38 2. 22 4. 58 1. 81 . 75 57, 22 3. 89
AID TO NO. 1245-01. 1 1011-1101		Jack hydraulic. Shackle. Tire recapping. Packing wood box. Wrench. 5315-741-0658 Pin. Gasoline. Oil engine No. 10. Oil engine No. 30. Oil gear. Oil brake. Grease general. Grease bearing. Paint yellow.	LP LP LP LP REP REP LP REP LP REP REP LP REP REP LP REP REP REP REP REP REP REP REP REP RE	1 EA 4 EA 8 EA 1 EA 1 EA 1 EA 1 EA 1 L 1 L 1 L 1 L 1 L 1 C 1 C 1 C 1 C 1 C 1 C 1 C 1 C 1 C 1 C	6.11 3.78 156.67 0.71 2.44 3.00 1.44 1.92 1.39 0.96 .03 1.13 .68 6.09

deviations from any specifications cited in the contract or other related contract terms except those approved by the Contracting Officer or his authorized representative. I also hereby certify that this item is in good serviceable condition.

Yoshiki Tagawa, Project Manager, AID Operations, Japan Aircraft Mfg. Co., Ltd.