

Offhand I would say this is the almost perfect gore. This is the place that everybody seems to overrun. The curb should be tapered off, and they did taper off the leading edge. I would say this would be the perfect gore.



But this is what they do in my area. They have saturated these gore areas with heavy concrete stanchions. This particular guardrail was smashed into 2 years ago, and it is still lying there. I feel, at this point, I would like to say that we should have maintenance on our highways. They ought to replace the light pole in 48 hours if it is knocked down. The guardrails are given out by contract every year or every 2 years,

