
I would like to point out I think we should have a rule that whenever we pour concrete stanchions for any reason at all on our roadsides the guardrail should be installed with the concrete stanchions. This thing has been there for  $2\frac{1}{2}$  years, and we never put in a guardrail to protect it. They had good intentions, but we should install the guardrail before we pour the block. The motorist needs some protection.



These things are constantly being hit, as you see here.

