

You can see the impact point and the lack of adequate supports of the guardrail and the chain-link fencing.

