


The sign was mounted on a breakaway wooden post that absorbed none of the energy.



And this is the on-scene photograph of what happened. The mother was seriously injured and her baby that she held on her lap was killed. The driver had moderate to serious injuries and the child in the rear seat was not injured at all.

