

A car ran through this bridge railing and dropped about 30 feet. These particular bridge railings are made of aluminum alloy. I feel they have no business using this kind of material on a high-speed road.

Mr. W. MAY. These are different locations?

Mr. LINCO. Yes, many locations there.

