


And here you can see the base sticking out. The rail ends where the dot is. Someone slammed into that and knocked down a light pole.

Because you do not have continuous rail to utilize the full strength of the steel railing, we get a lot of unnecessary damage and the light poles are going down anyway.



This is what I am talking about, you see. That seems to be the standard installation.

