

Here also it was not bolted to the railing. Even though it was near it, that means nothing. You have to phase it out, and bolt it to the railing. Instead of getting a scratched fender, a car is badly damaged.



This is what you see. The material is there, but installed wrong.

