


This is an interesting situation where there is a sign to be put in here, and this first installation of rail was head on at the edge of the shoulder, and then there was some additional flare and additional length of rail that was laid out here. You can see the headwall down at that point, the earthfill across here, which more or less is a sign island.



Here, in this picture, you see the completed installation, the sign island. Here you see the flared blocked-out rail. Here you have no more blocks running up to the structure. That is the treatment at that point.

