


This is a section of the side rail also showing how people get into this area, like it or not. This is shoulder here and this is just dirt, churned up and muddy. Well, muddy certainly in wet weather, as these ruts tend to indicate. And I suspect that the performance of rail with that kind of surface in between cannot be too good.



There are washers on this median divider, which runs right down the middle of a fairly wide median, in the process, as you can see, of landscaping, completing work, finishing work on the median area.

