


Mr. PRISK. Here is another view of the same thing.



Here is the median side in a little more detail; 50 feet of rail.

Mr. CONSTANDY. Mr. Skeels, I was only going to add, these are all too typical. They are fairly common. They are not unusual.

Mr. WILKES. But I would like to observe it is in the right position. It is near the middle of the median and it is not at the edge of the paved shoulder.

Mr. CONSTANDY. That is true. I think that is worth while in light of a few of the pictures we have seen; it does leave something to be desired, however, the guardrail itself. Mr. Wilson, would you care to comment on this?

