


And here is the detail of that. The rail is blocked out. They use a steel post as an end post with a woodblock at this point; this gap is still with us [indicating].

Mr. CONSTANDY. The new work has the same deficiency we have seen on the old.



Mr. PRISK. Yes. This is a detail of the New York box beam type of rail, the sleeve shown here in the joint. This is recognized as one of the better types of railing.

