

Mr. PRISK. Here is still another illustration of that curb down at the bottom, the brush curb. And upon crossing another structure showing the guardrail approach here. In this instance there has been no final anchorage yet of the post up here at the structure.

The curb is in front of the rail, again not too desirable.

