

This is a closeup picture of the same thing. One thing you notice here is about a half-inch of rail left to take the strain at such time as the force is applied. I am a little bit surprised this would be cut quite so thin. That could not withstand very much of a blow.

