

784

And this is the other complementing condition, steel pole, steel base all the way down behind the rail, slight exposure of the footing.

