

Here it is at night and in a snowstorm—essentially at night—taken with a flash photo. Here you can see the base out of the ground somewhat more than desirable, and the steel post. Both are very close by an asphalt curb.

Mr. CONSTANDY. Mr. Prisk, how does that round pipe compare with an I-beam in strength? Does it present as much of a hazard as the I-beam?

