


this morning of how this performs when it is struck by a car. The pole goes over the top of the car.

Essentially this is the same kind of performance you get from this support. I think we have some pictures here. This happens to be in Ogden, Utah. This is the very first breakaway sign installation site in Utah.

This sign was being put in at the time of our visit. We did not see this particular installation at that time, but it was about that time, 2 months ago now, that this sign was put in. We are looking from the gore back toward the approach.



This is the way it looked as you drove into it, and you can see the breakaway supports here.

