

It is quite important this area be clear as far as visibility between the two roads is concerned. A driver coming down this roadway should be able to see traffic on this through lane as far back as possible in order to adjust his own speed and entry to the through lane.

To move on down to that gore, we find the exit sign here with rather heavy concrete footings sticking out of the ground.



And here we are—again the place here where the grading of the interchange probably could not be accommodated to make this a real safe place to run into, but it does not look like you have too good a chance of getting in there with those footings in the way as they are.

