


Here we are in Missouri, with a drop inlet in the median, again raised above the surrounding terrain, level of the terrain. This would constitute quite a hazard if hit.



Here, also in Missouri, is drainage carrying through a grade separation structure, a very common type of drain inlet. There is a vertical surface there perhaps 8 inches high to hit.

