

When we come out toward the rural section of this Rhode Island portion, we find this shaped wall, wing wall to handle the culvert which crosses the roadway at this point, which in fact does present a considerable hazard unless the grating is very carefully handled around that point. It looks to me like it is going to end up too high even so, particularly out in this area here. [Indicating.]



Here is the type of median drain, and an obstruction at the same time, seen on the Georgia project. This is going through a grade separation structure. And although the headwall has been cut off, there still does remain here a less than desirable facility for drainage, from the safety standpoint.

