


The median drainage is handled in a concrete paved ditch of this sort. Aside from the fact this has a rather sharp V at the bottom, I think it might be regarded as satisfactory.

A rounded bottom would probably be more safe, functionally.



At the side there is a sharper V ditch with a steep back slope, and as you can see, the erosion from this slope is beginning to fill up this particular drainage feature and certainly, from the standpoint of a car running into this type of a break in the slope, this is undesirable.

