

This picture is one on the Missouri project showing the shoulder, first paved 2 feet wide with an asphalt mat, then 8 more feet of treated material, and some slight oiling of the rounded surface. These slopes, as you see, are rather substantial as you move on down here. [Indicating.]

This is the type shoulder that they have. Not any too stable. We understand some additional work is to be done on this shoulder, and certainly is needed, because it is soft now, easily pressed in just walking on the shoulder.



Another view of this same shoulder on the median side, showing perhaps a little bit more transverse slope than is desirable. A shoulder should have a relatively light slope from the edge of the pavement over to this point. [Indicating.]

