
In this particular case it was knocked completely down. This has been experienced in several of them, particularly on the narrow two-post supports.



This shows the conversion of the base.

