




Mr. TURNER. That is correct, because this is a different installation from the newer one that we are talking about. We are certainly extending and enlarging on a different standard the design that we originally approved and paid for.

Mr. W. MAY. Mention was made of Highway Research Bulletin 81; did that not make all sorts of recommendations that were not followed here?

Mr. TURNER. That is correct. But it was not a part of the official original standard. It was a research report with recommendations in it.

Mr. W. MAY. Yes.

There is a large sign in a gore area and the experts have suggested that this is a hazardous installation, guardrail plus the sign. It is a massive support.

