

SAFETY RECOMMENDATIONS SUBMITTED DURING FISCAL YEAR 1965—Continued

Reference No.	Recommendation subject	Submitted	Page No.
5-RE-10	Reevaluation of tail rotor service life on Bell 47	To FAA Aug. 17, 1964	35
5-RE-11	Improve accuracy and survivability of flight recorders	To FAA Aug. 21, 1964	38
5-RE-12	Installation of lower coupling drive shaft on Hughes 269 helicopter	To FAA Sept. 1, 1964	45
5-RO-13	Depiction of towers and obstructions in attention-drawing manner	To FAA Sept. 9, 1964	50
5-RO-14	Designation of Alpena, Mich., control area extension on year-round basis and provision of ATC services	To FAA Sept. 23, 1964	52
5-RE-15	Advise owners through FAA general aviation inspection aids to insure proper cleaning oil filter cover on Cessna 205 aircraft	To FAA Sept. 28, 1964	56
5-RE-16	Reassess structural integrity of Hughes tail rotor drive shaft in models 269A and 269B	To FAA Oct. 1, 1964	59
5-RE-17	Modification to fire extinguishing system for lower cargo compartment	To FAA Oct. 9, 1964	71
5-RA-18	Transistor watches—Potential source of interference to aircraft nav aids	To FAA Oct. 15, 1964	76
5-RE-19	Action re self-sealing fuel tank cells Convair PB4Y-2 and World War II aircraft	To FAA Oct. 20, 1964	79
5-RO-20	Charting of Navy student jet training areas	do	82
5-RO-21	Correction of USAF flight information publication (approach chart)	To USAF Oct. 23, 1964	85
5-RE-22	Evaluate adequacy of S-62A fuel quantity gaging system design	To FAA Oct. 26, 1964, Dec. 30, 1964, and Feb. 17, 1965	88
5-RO-23	Team aerial agriculture application by 2 or more aircraft	To FAA Oct. 29, 1964	98
5-RE-24	Require use of shoulder harness and crash helmet, agricultural flying and other operations involving low and slow flying	To FAA Nov. 3, 1964	99
5-RE-25	Review maintenance and inspection procedures of Hawthorne-Nevada Airlines	do	105
5-RO-26	Standardization of in-runway lighting at John F. Kennedy International Airport	To FAA Nov. 5, 1964	111
5-RE-27	Study be initiated to determine defective weld inspection method in center section truss assembly, Bellanca aircraft	To FAA Nov. 17, 1964	113
5-RO-28	Use of smoke masks in Viscount aircraft	To FAA Nov. 16, 1964	118
5-RE-29	Require suitable modification for Brantly B-2 helicopter shock strut design	To FAA Nov. 18, 1964	120
5-RE-30	Reevaluation of icing of Kollsman pitot head	To FAA Nov. 19, 1964	123
5-RE-31	Effectiveness of FAA's surveillance policies of air carrier operators and methods of certifying approved repair stations	To FAA Nov. 20, 1964	127
5-RE-32	Appropriate inspection and rework procedures for B-707 main landing gear aft axle be made mandatory	To FAA Nov. 23, 1964	133
5-RE-33	F-27 emergency exit door, aft right side, require compliance with regulations; also establish inspection schedule to detect fretting of wing	To FAA Nov. 24, 1964	138
5-RO-34	That the depiction of altitude restrictions on the plan view of approach plates be included on the expanded profiles	To FAA Nov. 25, 1964	143
5-RE-35	Determine possible use of reinforced polyesters for protection in commercial aircraft and feasibility of such material	To FAA Dec. 1, 1964	147
5-RO-36	Revision of Jeppesen approach chart	To Jeppesen Dec. 24, 1964	148
5-RE-37	Consider a redesign of B-707 electrical system to prevent prolonged interruption of essential power	To FAA Dec. 30, 1964	159
5-RE-38	Modify Lockheed Jetstar landing gear emergency extension system	To FAA Dec. 31, 1964	164
5-RE-39	Advise operators Bell 47G-3 re power lag in Franklin 6VS-335 engines	To FAA Jan. 8, 1965	170
5-RE-40	Reevaluation nose gear mechanism design of emergency system B-720 and all other aircraft using similar systems	To FAA Jan. 15, 1965	173
5-RE-41	Use of lift strut as a step undesirable re Cessna 140, 150, 170, 180, 210	To FAA Jan. 27, 1965	178
5-RO-42	Hazards to air carrier personnel during handling of large jet aircraft	To FAA Feb. 2, 1965	182
5-RE-43	Improvement in fuel systems Convair 340 aircraft	To FAA Feb. 9, 1965	187
5-RE-44	Modification of Brantly B2A fuel pump drain line	To FAA Feb. 18, 1965	192
5-RE-45	Formation of industry-government task force to reassess current passenger safety procedures	do	197
5-RO-46	Markings on aeronautical charts of wire installations over land or water	To C. & G. Mar. 4, 1965	201
5-RO-47	Promulgation of information on location of emergency exits	To FAA Mar. 12, 1965	202
5-RE-48	Issue AD re B-727 inboard trailing edge flaps	To FAA Mar. 18, 1965	204
5-RE-49	Equip Hughes 269A having Vertx II-100 spray kit with baffle	To FAA Mar. 22, 1965	210
5-RO-50	Radar air traffic control procedures	To FAA Mar. 30, 1965	213
5-RE-51	Improvements in service time for R-2800 cylinders—Allegheny Airlines	To FAA Mar. 31, 1965	222
5-RO-52	Installation of computer-based digital displays of RVR information	To USWB Apr. 1, 1965	229
5-RO-53	Revision of pt. 3 of the CAR's with record to landing gear visual position indicator and stall warning aural signal	To FAA Apr. 5, 1965	232
5-RE-54	Changes in fuel selector system, Lockheed 18	To FAA Apr. 8, 1965	250
5-RE-55	Expedite FAA approval and mandatory required fuel surge, tank detection, and suppression system for B-707; reorient FAA's lightning group	do	255
5-RE-56	Require mandatory installation of reverser in transit light to assist crew detection of hazardous asymmetrical thrust condition	To FAA, Apr. 21, 1965	259
5-RO-57	Revision of flight manual for Hughes helicopter to include information on "low fuel" warning light	do	265
5-RE-58	Conduct fleet campaign to determine if contaminated Ledex relays are installed in other L-1049H aircraft	To FAA, Apr. 22, 1965	269
5-RE-59	Classify certain sprays as "hazardous" both in general and air carrier aviation	To FAA, Apr. 26, 1965	276