

Control Measure IV - (Mine closing measures)

- 4-1 Mine working plans
- 4-2 Mine sealing which inundates the coal seam and other acid-producing strata
- 4-3 Watertight seals
- 4-4 Removal, burial or submergence of acid-producing refuse in strip or auger operations

- 4-5 Covering of coal faces in surface mining
- 4-6 Submergence of coal faces in surface mining

Control Measure V - (Chemical treatment of acid mine-drainage)

- 5-1 Emergency circumstances requiring chemical treatment for protection of downstream water quality
- 5-2 Emergency circumstances requiring chemical treatment within mining operation