

10022 COMPETITIVE PROBLEMS IN THE DRUG INDUSTRY

FACILITY NAME	INSPECTION DATE	RELIED TO FDA, VA, PHS	DESCRIPTION OF VIOLATION
Ketchum Labs Amityville, NY	October 1972	October 1972	The overhead duct in the area used for sampling of raw materials was heavily laden with dust. In this area, raw material containers are opened for sampling and thus, dust could enter raw material. Ceiling tiles were loose and separated from the ceiling in the granulation storage area. No documented procedures were available for housekeeping and maintenance methods for cleaning production equipment.
Universal Oil Products East Rutherford, NJ	October 1972	October 1972	Reactors, vessels, and crystallizers are dirty. Outside surfaces and associated piping are rusty and covered with a black oily substance. Tank and piping asbestos insulation are in disrepair. These conditions represent a potential source of contamination. Scoops, hoppers, shovels, trays, dippers used in the handling of Procaine hydrochloride crystals are not cleaned promptly after use. These utensils are dirty and encrusted with product and are potential sources of contamination.