

COMPETITIVE PROBLEMS IN THE DRUG INDUSTRY 10023

COMPANY NAME ADDRESS	INSPECTION DATE	DATE OF FIVE YEARS	DESCRIPTION OF VIOLATION
Packaging Corporation of America Vernon, CA	October 1972	November 1972	Toilets open directly to the manufacturing area.
Lypho-Med, Inc. Chicago, IL	November 1972	November 1972	Failure to perform complete monograph testing of propylparaben, lot NMO68, and methylparaben, lot RL4155 in accordance with the company's written test requirements. Loss on drying for each raw material was not done as required.
Zenith Laboratories Northvale, NJ	February 1973	February 1973	Failure to maintain building free of insects. A live cockroach was noted in the raw material storage area. The general appearance of the "Quarantine Area" reflects a lack of adequate janitorial service. It was heavily laden with dust and evidence of spilled raw material. It is not orderly and not arranged to facilitate cleaning and handling of containers.
Reine Pharm. Corp Roosevelt L.I., NY	March 1973	March 1973	The Technical Quality Control Director is not a full time employee and may be absent, due to family commitments at home, as noted during the survey visit. There is no designated assistant to assume duties of the Quality Control Director in the temporary absence of the Technical Quality Control Director. The plant was in poor state of repair. Observations included a cracked wooden floor in the receiving department and leakage from ceiling in the liquid fill area. Pools of water in the filling room were noted that could be tracked from one room to another. The floor drain appeared clogged with water from the leaking roof with water up to level of the drain cover.