## MAINTENANCE REQUEST

## SECTION 1

Control number; Aid to no. 4184–15.

1a. Organization; Aid EPRO No. 5, c/o, American Embassy, Tokyo.

3. Noun Nomenclature; Truck cargo 2½ ton 6x6 w/o winch, M211.

Acq. cost 5,993.
Rehabilitation on AID work specifications, Appendix A, Contract AID/csd/1129 (Estimated total man-hours: 253.00).

## SECTION II-WORK ACCOMPLISHED

Repair organization/activity; Japan Aircraft Mfg. Co., Ltd. Location; No. 3175, Tomiokapcho, Kanazawapku, Yokohama, Japan.

[Total man-hours, 357; total man-hour cost, \$597.44; total parts cost, \$784]

Description	Man- hours (hours and 10ths)	Federal stock No.	Parl sourc code	e Quantity	Parts y cost
ENGINE AND ENGINE COMPONENT		Motor wiper	_ N/C	2 EA	0
opitiig.	2. 00	2520-741-1511 Cone	115.7	ULA	2.020
Clean air cleaner of reservoir base and element				1 EA	5. 01
Popoir incorptive fuel nume service	1. 00	2520-741-1523 Piston	REP	1 EA	8, 90
Repair inoperative fuel pump capacitor with re-	F 4 18	2520-741-1649 Gasket	REP	1 EA	4. 03
placing terminal plate assy, fuel pump elbow	11	2520-708-4043 Sleeve	REP	1 EA	3, 88
and cable with cleaning work.	4.00		REP	20 EA	.40
Clean fuel tank and line, replace fuel tank unit	4. 50		REP	1 EA	. 17
그리는 이 그렇게 맞는 것 같다. 그리고 있는 것이 된 나도 하다		2530-287-8252 Bleeder	REP	12 EA	3. 84
Replace unserviceable muffler and mounting	1.00		REP	Î EA	. 11
clamp.		2530-350-7493 Cup	REP	Î ĒA	2. 10
Replace corroded rear, upper and lower exhaust	3, 00	2530-537-2176 Line	REP	Î ĒĀ	. 34
pipes with packing seal.		2530-537-2210 Kit	REP	ÎĒĀ	. 25
Perform engine compression tests	1 50	2530-560-8485 Brake	REP	1 EA	5, 39
Cyl. No. 1 2 3 4 5 6		2530-693-1028 Nut	REP	3 EA	
Comp. (psi) 113 113 120 120 113 113		2530-737-6444 Wheel	REP	1 EA	1.08
110 110 110		2530-741-0810 Hose			6. 39
INSTRUMENT AND ELECTRICAL SYSTEM		2530-741-0010 HUSE	REP	1 EA	1.00
MOTHOMENT AND ELECTRICAL STATEM		2530-741-2065 Cyl	REP	12 EA	39. 24
Check speedometer of its function at rod test	. 50	2530-741-2105 Brake	REP	2.25 FA	6. 86
Check ammeter of its function after engine repair	. 50	2540-050-0810 Arm	REP	2 EA	1.40
Replace defective oil pressure sending unit and	3.00	2540-050-0813 Blade	REP	2 EA	. 54
water temperature gage sending unit, then serv-	0.00	2540-699-9381 Chain	REP	1 EA	
ice all gages and other sending units.		2540-734-2196 Arm	REP		. 80
Check and repair generator of its function after	2,00	2540-741-0600 Cover		2 EA	4.80
engine repair.	2.00		REP	1 EA	5. 35
Replace defective harness at regulator-generator.	0.50	2540-741-0601 Cover	REP	1 EA	5. 15
Corvine ineperative headlight most as light blad	9. 50	2540-741-0602 Cover	REP	1 EA	3.68
Service inoperative headlight, marker light, black-	6. 50	2540-741-0603 Cover	REP	1 EA	2.77
out taillight and their wiring.		2540-741-0638 Fastener	REP	10 EA	. 50
Repair switch for bad contact	1.50	2540-741-0694 Cover	REP	1 EA	10.17
		2540-737-6110 Handle	REP	1 EA	1. 01
		2540-952-7035 Mirror	REP	2 EA	1. 28