

TM item No.	Sta- tus	Deficiencies and shortcomings	TM item No.	Sta- tus	Deficiencies and shortcomings
1	(*)	Replace 2 each battery, 12 volts.	12	(**)	Clean out painted rust and dirt and lubricate after; all control levers, shafts, rods, pins and cables.
2	(*)	Replace clamps, battery cables.	13	(**)	Remove dirt, paint and rust on conical rollers and turntable.
3	(**)	Control cable, engine stop frozen.	14	(*)	Lubricate idler wheels and rollers; deprocess and test electric power unit.
4	(*)	Fill up coolant in radiator.	15	----	Deprocess and test electric power unit.
5	(*)	Adjust fan belt and generator settings.	16	(*)	Replace all cabin bulbs and all top floodlights missing.
6	(*)	Install boom and extension assemblies.	17	----	Clean off all dirt and lubricate turntable and swing gears.
7	(*)	Replace boom mounting pins; bridle assembly, suspension cables.			
8	(**)	Replace boom cable; rusty and worn out.			
9	----	Track shoes and pins worn out and track shoes corroded; frozen.			
10	(**)	Sprockets, track shoes worn out.			
11	(*)	Lubricate sprockets and chain drive.			

*Damage/pilferage after receipt in Vietnam.

**Condition when received in Vietnam.

EQUIPMENT INSPECTION AND MAINTENANCE WORKSHEET NMC #25145
DETERMINED IN ACCORDANCE WITH DIAGNOSTIC PROCEDURES AND STANDARDS IN
THE TM CITED HEREON

8a. Signature (Person(s) performing inspection): Mr. Borja, TCN, Maint.
Branch, USAID/LOG.

9a. Signature (Maintenance Supervisor): David May, Maint. Branch, USAID/
LOG.

TM item No.	Sta- tus	Deficiencies and shortcomings	TM item No.	Sta- tus	Deficiencies and shortcomings
1	(*)	Seat as is, operator missing.	8	(**)	Clamp exhaust pipe extension missing.
2	(*)	Ignition switch missing.	9	(*)	Power unit floodlights missing.
3	(**)	Starter button switch missing.	10	(**)	Left chain loose.
4	(*)	All wires broken and disconnected, rewire.	11	(**)	Track shoes and pins worn out.
5	(*)	Battery missing.	12	(**)	Track shoe sprockets worn out.
6	----	Radiator leaking.	13	(**)	Roller bushings worn out.
7	(*)	Boom assembly, mounting pins, hook block, suspension cables, cable and pins assembly boom stop missing.	14	(**)	Oil leaking excessively on tracks drive box.
			15	(*)	Bulbs, floodlights, and cabin lights missing.

*Damage/pilferage after receipt in Vietnam.

**Condition when received in Vietnam.

EQUIPMENT INSPECTION AND MAINTENANCE WORKSHEET NMC No. : 10464

1. Organization: USAID Log. Div./MMB.

2. Name and model: Carrier Crane LO/TGN 8x8 Thaw Co.