

			Wrecker truck (serial No. 5043).	after partially repairing, but unable to obtain sufficient parts to fully repair; KOMEP records show quantity of 8 trucks, 9 were physically seen and 1 other reported as previously returned.
		1	D-8 bulldozer (serial No. 8R2508).	Operable; in process of being returned to KOMEP.
Milkum iron mine.....	1	1	1/4-ton utility truck (engine No. 48556).	Inoperable; mine personnel claim under repair.
Munkyeong coal mine.....	1	1	500 CFM air compressor (serial No. 13286).	Repaired; operating under temporary license issued by local police.
Sangyong limestone mine.....	2	2	2 1/2-ton dump trucks (serial and engine numbers not readable).	Inoperable; mine personnel claim being repaired.
Kangwon limestone mine.....	1	1	5-ton crane (serial No. 6558).	Inoperable; mine personnel claim they are unrepairable; not used since receipt during October 1963.
"	3	3	5-ton tractor trucks (serial Nos. 324052, 522888, 524757, 522919, 523937).	Inoperable; at mine site since Nov. 1964; mine personnel claim never used and
Dai Han Coal Corp. (Kangwon Provincial Forest Office).	1	1	10-ft. extension boom for crane.	Major repairs have been made; 2 currently under minor repair; not licensed, but in process; in limited use at mine site.
Samchok coal mine.....	2	2	3/4-ton cargo trucks (serial and engine numbers not readable).	Operable; in storage for undeterminable period.
Jungdong coal mine.....	4	4	2 1/2-ton dump trucks (engine Nos. 55864, 147572, 685272, 581716).	Repaired; not licensed; in limited use at mine site.
Dongwon coal mine.....	2	2	1/4-ton utility trucks (serial Nos. MD-39849, MD-11380).	Reported by mine personnel to be in Pusan; found there in highly cannibalized condition. One other truck (as noted on schedule 1) not located.
	1	1	3/4-ton cargo truck (serial No. 181763536).	Not located at mine site, but seen in Seoul operating under private licenses.
	2	2	2 1/2-ton dump trucks (serial Nos. 438850, 409001).	Repaired; not licensed; in limited use at mine site.
	1	1	5-ton tractor truck (serial and engine number unreadable).	Originally repaired and used at mine site; prior to being licensed involved in accident; in very poor condition.
Woojan coal mine.....	1	1	250 cfm air compressor.....	Cannibalized and used as spare parts for other trucks.
	3	3	2 1/2-ton dump trucks (engine Nos. 270252800, 270150914, 270812438).	Not used due to poor condition.
	2	2	5-ton dump trucks (serial and engine numbers unreadable).	One under repair at mine site; two located in Pusan in storage in poor condition.
Nonsan Limestone Mine.....	1	1	210 cfm air compressor (engine No. 30271145).	Cannibalized; reported by mine personnel and KOMEP as obtained for that purpose.
	1	1	5-ton tractor truck (serial No. 524033).	In good condition; not being used due to low ore production.
	1	1	12-ton semitrailers.	Repaired; not in use; awaiting licensing of truck—reported as in process.

INCREASE IN PRODUCTION OF MINERALS

Distribution of report

ROKG:
EPR

Number
of copies