

There is some work leading you to believe that we might go higher in mounting luminaires so as to cover situations of this sort; but simply attempting to light everything from the median side is not always a satisfactory solution.

Mr. W. MAY. Mr. Linko, you had another point. That sign support, the sign 278, could have been located behind that concrete bridge parapet on the right?

Mr. LINKO. Yes, behind the concrete wall. They always seem to put it someplace where somebody is going to hit it. It could be put behind that, or on the light pole, or in the center divider, putting them back to back. It would save on installation and constant maintenance.

Here also you see another sign, 21½ by 3-inch angle irons, saturating the shoulder.



Here you see the same sign mounted on the wall. Now, the reason this is mounted on the wall is because there is no room to put it on the ground. I feel if you can get something off the shoulder area, it should be mounted on the wall.

