


Here you can see the guardrail protecting the first post on a downhill turn, and there is a tapered curb. They must not be interested in the other three posts. That guardrail has been damaged and it is being replaced at this time. They still neglect to see the other three posts, and it was replaced just the way it was before. The rail is too short.



Here you see three posts; the one with the dot, the middle one, has been hit; there is a black spot on it near the bottom. This is Interstate 287; we fail to provide sliding action and protection at these poles.

