

Mr. MAY. It has been hit?

Mr. LINKO. Yes. With no maintenance. There is no driver decision to be made on the right-hand side. But in the gore area, a guy may decide to go left or right, and that is where they are overrunning it. Without spending any extra money, and just by thinking about the situation, it could be improved and made safer. I wish they would remove this hazard.

Here you see where they did something similar to what I recommended. Keep the thing on the right. And you can see the gore area,



there was a light there, somebody smashed it. It could have been the stanchion they hit.

This is another shot of the gore area, same spot. Even the light poles should be considered for the right side.

