


Notice that here is the edge of the roadway, and this setback is probably 10 feet or so [indicating], but this is a very inadequate design. There are many protuberances sticking out all along here. If you miss the first one, you have the second and the third.

This was built at the time that there had been publications in highway literature on a bridge rail design.

This is an expressway turnoff well marked, heavily signed. There is inadequate guardrail around the base of the signpost. But 1 day the individual did make this turn, a 17-year-old young man driving his parents in a brand new car, and he swung a little wide. You cannot



really see it, but the road edge is right here [indicating], along here. He swung wide and got into this area

