

It had snowed during the night. He skidded along the guardrail, which performed like it should; it held, it kept him on track—but the thing is that a few of the legs in here [indicating], near this end, were loose. The car snagged on the guardrail. It then spun around and the left rear door hit the cement monolith, here at the end of the guardrail, crushing the door in, killing the father in the rear seat, and the mother in the rear seat was ejected out the opposite door and down this embankment. She suffered serious injuries.

Had we had these legs implanted more strongly so that it would not rock and snag the car, and possibly the overlap of guardrail over the end here [indicating], this possibly would not have been a fatal accident.

This is the side impact against the door next to which the father was seated.



I am standing under an overpass. This is an expressway again. This car (at right in photo) went out of control one early morning. He was

