

towing another vehicle. You can see the tracks as he came sliding sideways into the exposed end of this very short section of guardrail, which crushed in the door, killing the driver.

The passenger in the rear seat and the passenger in the front seat did not receive any injuries.

This was repaired in the identical manner to the way it had been set up before the impact.

And this is an overview from the overpass. Notice that he only took off about one or possibly two support legs, crumbling the guardrail.

