

one stone; let's put it that way. Notice the bridge abutments are not protected. Everywhere I see the new work, it seems to be that they are only doing one thing at a time.

Here you can see you have four targets. You have the two rail ends and two bridge abutments.



And here you see a gore area really saturated. Not only did we put the concrete stanchion there, but we put three high voltage transformers there. Some big truck is going to run in there and damage that at

