


slide, there is plenty of guardrail to protect it. The guardrail is the hazard, not the aluminum light pole.

The reason I am showing you this picture is to suggest why could we not protect the tree also? You need a guardrail right down that line to protect all those trees. If you notice, this is an outside turn.

I would like to see the new money that we are spending now on guardrails used wisely.

Here you see a center divider. I feel when they put it here, they measured and put it exactly in the center. I think they could have gone around the tree. You can see the scar where it has been hit many times.

I did see the guardrail damaged and I saw the man replace it exactly where it was.



I want to bring out the point, even the new money we are providing for repair work or upgrading, we are using that either to do the job only half right, or again, are creating more hazards while we are doing it.

Here you see also trees in front of guardrails.

