


Here you see where they could use one pole and put an arm on either side, but they have two poles and they put one exactly where it is going to be hit, in front of the guardrail and right near the edge of the shoulder.



It made me mad as I watched them build this stuff. I read a book that tells them to put it 10 feet beyond the shoulder. Here they are putting it right back in the same old place. They are pouring a brand new foundation, not using the old base here. There is no excuse for it. They could have set these back. This is only a two-lane section, so they cannot say the luminaire arms are not long enough.

