

Here you have two targets. I feel we should go through all of these places and install another piece of rail on either side to provide sliding action. It might help save some light poles, and I am sure it will keep you from slamming into these ends and bases and give you serious damage.

Because these ends are not tied together, all of this unnecessary damage is caused. If it was done the right way you could have had a sliding action here.

