




When are we going to learn? Here, they tapered the box beam rail down to the ground which is what they should do ordinarily, but not at this location. If you drive along this rail, you are going to hit this base.

