

Here you have three separate pieces of equipment left on the road. The least they could do is put them all together. You would have one target. Here you have three separate targets. In fact, the right way is to take them up in front of the bridge abutment and put them behind there so you cannot hit them.



This guardrail is broken—has been for 2 years—and never replaced. Finally somebody came by and replaced it, but forgot to make a double rail and put the guardrail on this side for sliding action. The day they put it up somebody came by and wiped out the section there. They knocked down the light pole and ripped up the concrete abutment up farther. And it is the same way today, 4 months later.

