

The majority of them occurred from this point to just beyond the 270 route marker. This route marker is mounted on a 4-inch I-beam, and in checking the accident records I found that in April of last year:

This vehicle ran off the road and hit that 4-inch I-beam. It took that 270 marker off the I-beam.



The driver was injured, and again this is what those 4-inch I-beams can do to a vehicle.

