


This is the same bridge parapet I was talking about a few seconds ago. There are a number of things to note here. The full shoulder ends before the bridge. The guardrail comes back in toward the bridge parapet. There is a slight shoulder on the bridge. This is a raised curb, and a bridge parapet with guardrail not anchored.



This is that same bridge parapet which in November of 1966 was struck by a vehicle. The vehicle first hit the guardrail, and you can see the guardrail gave way. The vehicle was carried into the bridge parapet. In this particular accident, the vehicle then went across the road—through three lanes of traffic, and slammed into the bridge parapet on the other side, as seen in this picture.

