

This bridge is skewed somewhat. He was able to hit the parapet end of the other side of the bridge.



That accident was in November 1966. This photograph was taken in December 1966, 1 month later. This is the way the guardrail was installed after the accident.

In checking the records I found in January, 1 month after I took the last photograph, 2 months after the first accident, a man traveling in the same location went off the road, hit the guardrail which guided him into the parapet and he was killed.

