


Mr. O'HARA. This accident occurred last year on the Woodrow Wilson Bridge, and the reason I had not mentioned the shoulder before is because I was going to mention it here. The vehicle in front of this vehicle had a flat tire.

As you pointed out, there is no shoulder on the bridge and the motorist decided to change the tire on the bridge. Another vehicle approached from Maryland, and only saw the taillights of the stopped car and apparently assumed that the vehicle was traveling in the same direction. A rear end collision followed, resulting in injury to three people.



And this is the front of the car which ran into the stopped vehicle. You can see the spare tire sitting on the sidewalk, which the man was going to change.

