



Here is an installation we passed en route to the subject job. This is on I-71, near Cleveland, where there is a guardrail installation at an overhead sign bridge and it is rather short and moving up close to it you see what happened on the median side. This guardrail without the washers, as I said, was torn off the post.

